

# Illustrated Parts List - IPL Update



Product Name(s)

**T540XP11**

Description of change

A new Ignition module, 587 30 68-02, has been introduced to improve start behavior and idle speed. Problem with missing spark at start has been corrected. Incorrect speed detection causing uneven speed at idle has also been corrected.  
 If you encounter issues like this, we recommend you to change module.  
 Modules have been reworked/reprogrammed in production. Modules as spare parts are replaced with reworked/reprogrammed.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
S/n 20163600339	Valid for Ignition module 587 30 68-02.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Ignition system	1	587 30 68-02	Ignition module	587 30 68-01	

1. Reworked modules are marked.

